



# Recovery Cylinder Hydrostatic Test and Refurbishing Program

Refrigerant Recovery Cylinders require a Department of Transportation (DOT) hydrostatic recertification every 5 years. This requires the cylinder to have a visual, internal and external examination and a test by interior hydrostatic pressure in a water jacket for determination of the expansion of the cylinders. NRI is a DOT approved hydrostatic test facility and offers other cylinder refurbishing services. Below are details of NRI's cylinder refurbishing program offered to owners of recovery cylinders. *Please call for a quotation for any service not listed.*

## Hydrostatic Test Includes:

- Hydrostatic Test
- Internal Drying
- Test Date Affixed to Cylinder

CYLINDER SIZE	HYDROSTATIC TEST	
	Part Number	Suggested Retail Pricing
30 & 50	30/50HT	\$54.00
125	125HT	\$79.24
240	240HT	\$117.00
1/2 TON	1000HT	\$315.00

## Hydrostatic Test and Refurbish Includes:

- Hydrostatic Test
- Removal of Old Paint
- Application of Grey/Yellow Paint
- Test Date Affixed to Cylinder
- Dip Tube Replacement
- Internal Drying
- Dual Port Valve Replacement

CYLINDER SIZE	HYDROSTATIC TEST & REFURBISH	
	Part Number	Suggested Retail Pricing
30 & 50	30/50HTR	\$132.48
125	125HTR	\$227.70
240	240HTR	\$258.75
1/2 TON	1000HTR	\$693.00



Prices above are quoted on a "sight unseen" basis. Additional work may be necessary for DOT certification. Customer will be notified before work begins if additional costs will be incurred. Please call for pricing for any cylinder sized not listed.